


Löten Sei umlaufend einen Draht zur Verstärkung.  
 Solder a wire around the periphery for reinforcement.



85 110 02 Facette Straight 25,4 x 50,8 mm  
 Bevel Straight 25,4 x 50,8 mm

85 320 03 Spiegel-Facette 38,1 x 76,2 mm  
 Mirror-Bevel 38,1 x 76,2 mm

85 350 02 Spiegel-Facette Eckenpaar 38,1 x 101,6 mm  
 Mirror - Bevel corner pair 38,1 x 101,6 mm