

85 380 04

85 380 04

85 380 04


85 380 04

85 380 04

85 380 04

85 380 04

Löten Sie umlaufend einen Draht oder U-Profil zur Verstärkung.
Solder a wire or u-profile around the periphery for reinforcement.



85 380 04 Spiegel-Facette Dreieck 101,6 x 101,6 x 101,6 mm
Mirror-Bevel triangle 101,6 x 101,6 x 101,6 mm