


Löten Sei umlaufend einen Draht zur Verstärkung.
 Solder a wire around the periphery for reinforcement.



85 000 02 Facette Pencil 19,2 x 50,8 mm
 Bevel Pencil 19,2 x 50,8 mm

85 320 03 Spiegel-Facette 38,1 x 76,2 mm
 Mirror-Bevel 38,1 x 76,2 mm

85 200 07 Facette Halbkreis 152,4 x 76,2 mm
 Bevel semi circle 152,4 x 76,2 mm

85 350 02 Spiegel-Facette Eckenpaar 38,1 x 101,6 mm
 Mirror - Bevel corner pair 38,1 x 101,6 mm